UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO. : 7,804,557 B2 Page 1 of 1

APPLICATION NO.: 10/526233

DATED : September 28, 2010

INVENTOR(S) : Schanz et al.

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

Column 4

Line 10, after "second current signal" insert -- and sets the value of the lamp current signal--

Signed and Sealed this

Second Day of November, 2010

David J. Kappos Director of the United States Patent and Trademark Office